
Meridian 1

Meridian SL-1 data feature

Installation Apple and Hewlett-Packard

Document Number: 553-2731-201

Document Release: Standard 1.0

Date: December 1994

© 1985, 1994

All rights reserved

Printed in the United States of America

Information is subject to change without notice. Northern Telecom reserves the right to make changes in design or components as progress in engineering and manufacturing may warrant. This equipment has been tested and found to comply with the limits for a Class A digital device pursuant to Part 15 of the FCC rules.

SL-1 and Meridian 1 are trademarks of Northern Telecom.

Revision history

December 1994

Standard, release 1.0. The following two documents have been combined to create this document.

- *Apple-Macintosh Interface installation* (553-2731-200, Appendix 2)
- *Hewlett Packard Interface installation* (553-2731-200, Appendix 3)

This document replaces these two appendices.

Contents

Apple Macintosh Interface	1
General	1
Equipment interface	1
Related Documents	1
Installation	2
Without telephone	2
With telephone	2
 Hewlett Packard Interface	 5
General	5
Related Documents	5
HP3000 ATP	6
Installation	6
Fault clearing	7

List of figures

Figure 1	
Macintosh to SL-1 connection—without telephone	3
Figure 2	
Macintosh to SL-1 connection—with telephone	3
Figure 3	
QPC430D faceplate	10
Figure 4	
HP3000 Meridian SL-1 host connection	11
Figure 5	
Signal path—HP3000 to Meridian SL-1	12

List of tables

Table 1	
Breakout box wiring	8